Your task has been submitted.

Project Number: 070901

Project Name: Facilities Services

Task Number: 114515

Task Name: Room Renovation

Requester Information

Project Number: 03TM00

Employee Nbr: 102890 Name: BARLOW, EDWARD C

Task Number: **4.9.01**

Mail Stop: 198-219

Phone: (818)354-3585 Org: 3454

Task Status: New

Request Date: 18-MAR-2002

Description: Request cost and time required to renovate 198-B5.

Comments:

REQUESTER INFO

Request entered by BARLOW, EDWARD C (Emp. #: 102890).

CUSTOM FORM DATA

Funds_Cog_Name = Ron Murillo. Funds_Cog_Phone_Number = 4-4177.

Requested_Completion_Date = 06-30-02.

FROM COMMENTS FIELD

Need estimate for work entailed with removing two non bearing walls that currently separate 198-B5 from B5A and the associated work outlined below. Removial of a cold water air conditioning unit from B5A. Installing floor tiles to fill the resulting void as well as replacing the tiles currently being used as vents. Estimate whether air handler ceiling vents need to be moved or additional vents installed. Celing mounted lighting reconfigured to match existing lighting in B5. Removial of two ckt breaker switch pannels from one of the walls that will be removed.

These control two vertical power strips on an adjacent wall. Ed Barlow @ 4-3585

Use Ctrl-P to print.

This page was dynamically produced by the **PL/SQL Agent** & **Oracle** database on March 18, 2002 04:33:17 PM



